

Replacing insert and liner














What was left of the rusted out pipe





Someone did a real Hack job
on the heatalor









Black steel pipe was used and no weatherproof chase chap.
Water ran down the Masonry chimney



Only part left of the Old Black Steel liner was the liner blanket
The rest crumbled down into the smoke self.



















